

47




FIG.1




FIG.2




FIG.3A




FIG.3B




FIG.4A




FIG.4B

09888091.101901




FIG.5




FIG.6A




FIG.6B




FIG.6C




FIG.6D

09888061.101901




FIG.7





FIG.8




FIG.9




FIG.10

00883031-1010101

FIG.11 19088860






FIG.11

0988890611091001



1050101-19088850




FIG.13




FIG.15 FIG.15





FIG.15

FIG. 16



09888651-1050-4





FIG.17A

09888051 - 101901






FIG.18A




FIG.18B




FIG.19




FIG.20

105101-T9088860




FIG.21A




FIG.21B

TOP SECRET // R9088860




FIG.22




FIG.23A





FIG.23B

**FIG.24B**






FIG. 25
(PRIOR ART)

ФОТОФУРТ™ Т910833860






FIG.28
(PRIOR ART)

F06T07" T9088860




FIG.29
(PRIOR ART)




FIG.30
(PRIOR ART)

F0610107 T9088860




FIG.31
(PRIOR ART)




FIG.32
(PRIOR ART)




FIG.33
(PRIOR ART)





FIG.35
(PRIOR ART)

09888051.1011901




FIG.36
(PRIOR ART)




FIG.37
(PRIOR ART)




FIG.38
(PRIOR ART)




FIG.39
(PRIOR ART)





FIG.40
(PRIOR ART)



F06F0F "T90888860




FIG.42
(PRIOR ART)




FIG.43




FIG.44




FIG.45

TO TOT T9088860




FIG.46

Y06Y0F" T90B8860

Note: "Ringing" mode missing




FIG.47A

Connection

TO TOTOT "T9088860

Note: Missing event record




FIG.47B




FIG.48

TUTOR TUTOR TUTOR




FIG.49

Network Interface

X

Y

K06T0T" T9088860




FIG.50

F06F07-F9088860




FIG.51A




FIG.51B

09888651.101901

T05T0T" T9088860




FIG.52A

TTTTTTT TTTTTTTT




FIG.52B




FIG.53A





FIG.53B


00000006.1.101501



Complete evolution diagram

FIG.54A


098888051 - 101901



After states on C_2 's middle and
bottom trace are clustered

FIG.54B


10190119088801



After some of C₁'s
events are clustered

FIG.54C

TOE101.T988860



09888051.101901




FIG.55A




FIG.55B